




PPN50Xi





= 1250 (-5°C°)



PPN50Xi

Ø = 4 mm

L = 35 - 40 - 50 mm

Hardened Ring Nails





		15 min.	2 500 max.
		60 min.	10 000 max.
		90 min.	13 000 max.





25%	50%	75%	100%
☐	☐	☐	☒
☐	☐	☒	☒
☐	☒	☒	☒
☒	☒	☒	☒







0 → 300	☐
	☐
	☐
	☒



-15°C	1 000 /hour
≤ T ≤	
+49°C	3 300 /day


















50 000 BANG!





RESET



Resting position / Ruheposition / Position de repos / Ruststand / Posición de descanso / Posizione di riposo / Posição de descanso / Pozycja spoczynku / Klidová poloha / Nyugalmi állapot / Положение в нерабочем состоянии / Θέση αδράνειας / Hvilestilling / Viloläge / Hvileposisjon / Lepoasento / Položaj mirovanja / Pokojová poloha / Položaj mirovanja/ وضع الشكون / Ramybės padėtis / Ootestasend / Miera stāvoklis / Hvíldarstaða



Notes





PPN50Xi

Ø = 4 mm

L = 35 - 40 - 50 mm

Hardened Ring Nails



Route de Lyon F-26500 Bourg-lès-Valence

019691-1
03/2020