




**Paslode®**  
**Impulse®**

**IM65 F16 Lithium**  
**IM65A F16 Lithium**  
**IM50 F18 Lithium**





**Paslode**  
Impulse



= 1000



**Paslode**  
Impulse




**IM65 F16**  
L : 16 ▶ 63 mm  
F16 Gauge



**Paslode**  
Impulse



**IM65A F16**  
L : 16 ▶ 63 mm  
F16 Gauge



**Paslode**  
Impulse



**IM50 F18**  
L : 16 ▶ 50 mm  
F18 Gauge



**Click**



**Click**



**Paslode**  
Impulse



= 10000 max





15 mn = 2000 max  
60 mn = 8500 max  
90 mn = 10000 max  
2 mn = 200


























**1000/hour  
4000/day**














16



17




18



19




20



21




22




23



24



25



26



27