




TOOL SHED




x1




x1





x1



x1




x1

 x^2 


x1




x1




x1



x1




x1




x4

 x_2 

x2



x1



x1




x2



A - Ø4x50
x48



G
x1



B - Ø3.5x25
x60



H
x1




C - Ø3.5x16
x34




I
x1



D* - Ø7x40
x8






E
x4




F
x1




*DEPENDING ON CONFIGURATION





Ø6





K2







A
4x50 x7





K4





A  4x50 x7



B  3.5x25 x6





K5





A
4x50 x14





K6





A
4x50 x8




K7






A 
4x50 x4




K8




A
4x50 x8



K9





+






C 3.5x16 x16
D* 7x40 x4

E x4
G x1

H x1
*DEPENDENT ON CONFIGURATION




+





+



B  3.5x25 x16





C  3.5x16 x10

D*  7x40 x4



F  x1

I  x1

*DEPENDENT ON CONFIGURATION



+



K11